Each

Thursday, 17/07/2008 11:47:33 AM Date: Julie Lecocq User: **Process Sheet Drawing Name** : SEAT PAN (AFT FACING LH/RH) : CU-DAR001 Dart Helicopters Services Customer Job Number : 40587 : 13362 **Estimate Number** : D37741 **Part Number** P.O. Number : D3774 REV A- B S.O. No. : **Drawing Number** : 17/07/2008 This Issue : N/A **Project Number** : NC Prsht Rev. R&D THERMOFORMING : A B . First Issue : // Type **Drawing Revision** : 39703 Material **Previous Run Due Date** : 31/07/2008 Written By Checked & Approved By New Issue 08.06.04 DL verified by:DD Comment : Est. REV:A **Additional Product** Job Number: Description: Seq. #: Machine Or Operation: HAND FINISHING THERMOFORMING 1.0 HAND FINISH TH Comment: HAND FINISHING THERMOFORMING Set up machine program D3774-1 Set up clamping frame as per folio M 105 330 GE PLASTICS LEXAN SHEET **6** ★ MLEXS125F6002904 IX MLEXS 093 FG00607 MC05494 21.3340 sf(s) Comment: Qty.: 10.6670 sf(s)/Unit Total: GE PLASTICS LEXAN SHEET Wh 08.07.18. HAND FINISHING THERMOFORMING 3.0 Comment: HAND FINISHING THERMOFORMING 6× 32'x 44" 1) Cut Blanks

THERMOFORMING MACHINE

08.07.18

Comment: THERMOFORMING MACHINE

THERMOFORMING

Thermoform as per Dwg. D3774-1and Folio 🖘

ΘL.

Dwg. Rev. Folio Rev.

4.0

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr/	Approval QC Inspector
08.07,(8	3 4	Pull I additional port with MLEXSO 93 F600607 to be used for structural test.	st.	og.07.18	l	12 FE - 25	/www.
	0						

Part No: <u>D3774-1</u>	PAR #:	_ Fault Category:	NCR: Yes No DQA:	Date: <u>08.08.21</u>
			QA: N/C Closed:	Date:

NCR:40	587	W	ORK OR	DER NON-CONFORMANCE	E (NCR)			
		Description of NC		Corrective Action Section B		Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
<u>०८ घटा</u>	4	Not used for Tost	08.08.17 52047	Scrap à destrap	B.C. 1)	//	185 042 08.000R	
		(WAITE)			Wh.	1605-12	08.040	1608-12
08081J	8	(cent used for 5 twetwal test.	े स्टा इस्	Do Net USO. Retain for R+D.	W/ 88.08.0		or the second	
	0,	Structural test.	08.08.12	Part and a second	EK.Os.	100012	03.0510	13811
			•					•
			,					

NOTE: Date & initial all entries

Date: Thursday, 17/07/2008 11:47:33 AM User: Julie Lecocq **Process Sheet** Drawing Name: SEAT PAN (AFT FACING LH/RH) Customer: CU-DAR001 Dart Helicopters Services Part Number: D37741 Job Number: 40587 Job Number: Seq. #: Description: **Machine Or Operation:** INSPECT PARTS AS THEY COME OFF MACHINE 5.0 QC2 DL 08.07.18. PARTS AS THEY COME OFF MACHINE Comment: INSPECT HAND FINISHING THERMOFORMING HAND FINISH TH 6.0 Comment: HAND FINISHING THERMOFORMING 1) Trim to Finished Dimensions 7.0 QC2 Comment: INSPECT TRIMMED PARTS 1) Check dimensions to ensure conformity to drawing tolerances 8.0 QC5 Comment: INSPECT WORK TO CURRENT STEP APACKAGING RESOURCE #1 PACKAGING 9.0 Comment: PACKAGING RESOURCE #1 FINAL INSPECTION/W/O RELEASE 10.0 QC21 Comment: FINAL INSPECTION/W/O RELEASE Job Completion

Dart Aerospace Ltd

W/O:		WORK ORDER CHAN	GES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					,		
Part No	:	PAR #: Fault Category:	NCR: Yes	No DQ	A:	Date: _	
			QA:	N/C Close	d:	Date:	

NCR:			WORK ORD	ER NON-CONFORMANO	CE (NCR)			
		Description of NC		Corrective Action Section B		Verification	Annessal	Annroval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
				ℓ				
•								

NOTE: Date & initial all entries

DART AEROSPACE LTD	WORK ORDER:	40587
Description: Seat Pan (Aft Facing)	Part Number:	D37741
Inspection Dwg: D3774 Rev:		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

First Article] Prototype

(Step 4) Thermoforming Visual Inspection Sign-off

Description	Initials
Acceptable shape definition	135
Free of visual flaws (bumps, cracks, voids, etc.)	BR

(Step 6) Trimming FAI Checklist

Inspect dimensions highlighted on inspection sheet drawing _____Rev. __ and record below

REUISED	Drawing	Tolerance	Actual	Accept	Reject	Method of	Comments
DIMENSIO	್ರಳುDimension		Dimension			Inspection	
ŀ	1.3"	+/- 0.100	.123				
	33.9"	+/- 0.100	33.9	· ·			
· e85	0.100" 7	MIN	.67				
. 100	0.135"	MIN	١١١١		·/		
100	0.135" Y	MIN	. 111				
.100	0.135"	MIN	1111				
,100	0.135"	MIN	. 121				
•	17.4	MIN	17.5 1	~			
	4						

Measured by:	Audited by:	Prototype Approval:
Date: 0x/07/24	Date: 130725	Date:

Rev	Date	Change	Revised by	Approved
		New Issue		

DART AEROSPACE LTD)			WORK	ORDER:	40587	
Description: Seat Pan (A	Aft Facing)			Part	Number:	D3774	1_
Inspection Dwg: D3	774 Rev:					Page 1 c	of 1
	P 00.0	1.86		-			:
	-		TON OU	TOTAL			Ť
	FIRST ARTIC	LE INSPECT	TON CH	ECKLIS	T		
	⊠ First	Article [Protot	tyne			•
*2				type			•
	(Ste	p 4) Thermo	forming	<u>.</u>			i.
		al Inspection					12.1
	V 1000	ar mop conon	21811 01				
							15.
Description						Initia	s
Acceptable shape definit	ion						
Free of visual flaws (bun	and aracke voide etc.)					33	
Tree or vioual naws (our	ips, cracks, voids, etc.)		· · · · · · · · · · · · · · · · · · ·			18	-e-
Tree of violar news (our		Step 6) Trim	ming				
Inspect dimensions high		FAI Checkl	list	Rev a			
Inspect dimensions high		FAI Checkl	list		Method o	f Comn	lei
Inspect dimensions high	(Salighted on inspection s	FAI Checkl	list			f Comn	iei
Inspect dimensions high ed Drawing บริเจพวิ Dimension 1.3"	Tolerance	FAI Checklheet drawing	list		Method o	f Comn	her
Inspect dimensions high Ed Drawing US เอพวิ Dimension 1.3" 33.9"	Tolerance +/- 0.100 +/- 0.100	heet drawing	Accept	Reject	Method o	f Comn	101
Inspect dimensions high Lad Drawing US เอพว Dimension 1.3" 33.9" 5) 0.100"	Tolerance +/- 0.100 +/- 0.100 MIN	FAI Checkles heet drawing	Accept		Method o	f Comn	1ei
Inspect dimensions high Inspect dimension high In	Tolerance +/- 0.100 +/- 0.100 MIN MIN	FAI Checkles heet drawing	Accept	Reject	Method o	f Comn	iei
Inspect dimensions high Ad Drawing US 16N Dimension 1.3" 33.9" 0.100" 0.135" 0.135"	Tolerance +/- 0.100 +/- 0.100 MIN	FAI Checkles heet drawing	Accept	Reject	Method o	f Comn	101
Inspect dimensions high Ad Drawing US 16N Dimension 1.3" 33.9" 0.100" 0.135" 0.135" 0.135" 0.135"	Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN	FAI Check heet drawing _ Actual Dimension 1.23 33.525 ,42 129 115 116	Accept	Reject	Method o	f Comn	Tel
Inspect dimensions high Ad Drawing US 16N Dimension 1.3" 33.9" 0.100" 0.135" 0.135" 0.135"	Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN MIN	FAI Check heet drawing _ Actual Dimension 1.23 33.525 .42 123 115	Accept	Reject	Method o	f Comn	1ei
Inspect dimensions high Ad Drawing US 16N Dimension 1.3" 33.9" 0.100" 0.135" 0.135" 0.135" 0.135"	Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN MIN	FAI Check heet drawing _ Actual Dimension 1.23 33.525 ,42 129 115 116	Accept	Reject	Method o	f Comn	101
Inspect dimensions high Ad Drawing US 16N Dimension 1.3" 33.9" 0.100" 0.135" 0.135" 0.135" 0.135"	Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN MIN	FAI Check heet drawing _ Actual Dimension 1.23 33.525 ,42 129 115 116	Accept	Reject	Method o	f Comn	
Inspect dimensions high Ad Drawing US 16N Dimension 1.3" 33.9" 0.100" 0.135" 0.135" 0.135" 1.24	Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN MIN	FAI Check heet drawing _ Actual Dimension 1.23 33.525 ,42 129 115 116	Accept	Reject	Method o	f Comn	
Inspect dimensions high Ad Drawing US 16N Dimension 1.3" 33.9" 0.100" 0.135" 0.135" 0.135" 0.135"	Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN MIN MIN MIN	FAI Checkles heet drawing	Accept	Reject	Method o	f Comm	

Change New Issue

Rev

Date

Revised by

Approved

DART AEROSPACE LTD				WORK (ORDER:	40597
				2 ()	1	D27744
Description: Seat Pan (Aft	Facing)		•	Part	lumber:	D37741
Inspection Dwg: D377	4 Rev: 1					Page 1 of
	PH.	16.60-	-			*
	FIRST ARTIC		ION CH	ECKLIST	1	
162		 -	-			H.
*5	∑ First	Article _	_ Protot	ype		(1) 数
	(Ster	o 4) Thermo	forming			
		l Inspection				
	, 1544		8-8			
		<u> </u>				<u>'</u> .
Description						Initials
A accutable above definition			 -			BB
Acceptable shape definition Free of visual flaws (bumps						133
Troe of violation (cumps						
Tree of visual name (cumps		Step 6) Trim	ming			
Tree of violation (cumps		Step 6) Trim FAI Checkl				
	(5	FAI Check	list	Rev an	d record helo	DW
Inspect dimensions highli	(S ghted on inspection sl	FAI Check	ist			
Inspect dimensions highli	(5	FAI Check	list	Revan	Method of	OW Comme
Inspect dimensions highlightightightightightightightightightight	ghted on inspection sl	FAI Check	Accept			
Inspect dimensions highlighting Drawing Dimension 1.3"	ghted on inspection sl	FAI Check	Accept		Method of	
Inspect dimensions highlighting Drawing Dimension 1.3" 33.9"	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100	FAI Check	Accept	Reject	Method of	
Inspect dimensions highlighting Drawing Dimension 1.3" 33.9" 0.100"	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN	Actual Dimension 128 33.575	Accept		Method of	
Inspect dimensions highlighting Drawing Dimension 1.3" 33.9" 0.100"	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN MIN	Actual Dimension 28 33.575	Accept	Reject	Method of	
Inspect dimensions highlighting Drawing Dimension 1.3" 33.9" 0.100"	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN	FAI Check heet drawing _ Actual Dimension 128 33.875 .87 110 113	Accept	Reject	Method of	
Inspect dimensions highlighting Drawing Dimension 1.3" 33.9" 0.100"	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN MIN	FAI Check heet drawing _ Actual Dimension 128 33.875 . 87 110 113 119	Accept	Reject	Method of	Comme
Inspect dimensions highlighting Drawing Dimension 1.3" 33.9" 0.100" 0.135" 0.135"	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN	FAI Check heet drawing _ Actual Dimension 128 33.875 .87 110 113	Accept	Reject	Method of	Comme
Inspect dimensions highlights Drawing Signs Dimension 1.3" 33.9" 0.100" 0.135" 0.135" 0.135" 0.135"	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN MIN	FAI Check heet drawing _ Actual Dimension 128 33.875 .87 110 113 119	Accept	Reject	Method of	Comme
Inspect dimensions highlights Drawing Signs Dimension 1.3" 33.9" 0.100" 0.135" 0.135" 0.135" 0.135"	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN MIN	FAI Check heet drawing _ Actual Dimension 128 33.875 .87 110 113 119	Accept	Reject	Method of	Comme
Inspect dimensions highlights Drawing Si NN	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN MIN	FAI Check heet drawing _ Actual Dimension 128 33.875 .87 110 113 119	Accept	Reject	Method of Inspection	Comme
Inspect dimensions highlights Drawing Signs Dimension 1.3" 33.9" 0.100" 0.135" 0.135" 0.135" 0.135"	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN MIN	FAI Check heet drawing _ Actual Dimension 128 33.875 .87 110 113 119	Accept	Reject	Method of Inspection	Comme
Inspect dimensions highlights Drawing Si NN	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN MIN	FAI Check heet drawing Actual Dimension 128 33.875 .87 110 .113 .119 .115 ./2. 4	Accept	Reject	Method of	Comme ev B

Change New Issue

Rev

Date

Revised by

Approved

DART AEROSPACE LTD				WORK	ORDER:	40587
						D27744
Description: Seat Pan (Aft	Facing)			Part	Number:	D37741
Inspection Dwg: D3774	4 Rev: 🖋 🕜					Page 1 of
	PW 05.01	کرا				•
	FIRST ARTICLE		ION CH	ECKLIST	7	
			_			
1/1/	⊠ First Ar	ticle _	」 Protot	ype		
#	(64 1)	Tl	C			ì
/		Thermo		c		1
,	Visual In	ispection	Sign-oi	Ι		
						,
Description						Initials
Acceptable shape definition						933
						3
Free of visual flaws (bumps	s, cracks, voids, etc.)					200
Free of visual flaws (bumps	(Step	6) Trim	_			150
	(Step	AI Checkl	ist	Rev an	d record be	elow
Inspect dimensions highlig	(Step FA ghted on inspection sheet	AI Checkl	ist			
Inspect dimensions highlig	(Step FA ghted on inspection sheet Tolerance	AI Checkle drawing _	ist	Rev an	Method of	f Comm
Inspect dimensions highlig P Drawing บรางพ Dimension	(Step FA	Arawing	Accept			f Comm
Inspect dimensions highlig Drawing บริเอฟ Dimension 1.3"	(Step FA) ghted on inspection sheet Tolerance	Actual	ist		Method of	f Comm
Inspect dimensions highlig Drawing บริเอฟ Dimension 1.3" 33.9"	(Step FA) ghted on inspection sheet Tolerance +/- 0.100 +/- 0.100	Actual Dimension	Accept	Reject	Method of	f Comm
Inspect dimensions highlig Drawing Slow Dimension 1.3" 33.9" 0.100"	(Step FA) ghted on inspection sheet Tolerance +/- 0.100 +/- 0.100 MIN	Actual Dimension 1.23 33.575	Accept	Reject	Method of	f Comm
Inspect dimensions highlights Drawing Slow Dimension 1.3" 33.9" 0.100" 0.135"	(Step FA) Shted on inspection sheet Tolerance +/- 0.100 +/- 0.100 MIN MIN	Actual Dimension 1.23 33.575 121	Accept	Reject	Method of	f Comm
Inspect dimensions highlights Drawing Slow Dimension 1.3" 33.9" 0.100" 0.135" 0.135"	(Step FA) ghted on inspection sheet Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN MIN MIN	Actual Dimension 1.23 33.575 121	Accept	Reject	Method of	f Comm
Inspect dimensions highlights Drawing Slow Dimension 1.3" 33.9" 0.100" 0.135" 0.135" 0.135"	(Step FA) ghted on inspection sheet Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN	Actual Dimension 1.23 33.575 121 112	Accept	Reject	Method of	f Comm
Inspect dimensions highlights Drawing Slow Dimension 1.3" 33.9" 0.100" 0.135" 0.135"	(Step FA) ghted on inspection sheet Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN MIN MIN	Actual Dimension 1.23 33.575	Accept	Reject	Method of	f Comm
Inspect dimensions highlights Drawing Slow Dimension 1.3" 33.9" 0.100" 0.135" 0.135" 0.135"	(Step FA) ghted on inspection sheet Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN MIN MIN	Actual Dimension 1.23 33.575 121 112	Accept	Reject	Method of	f Comm
Inspect dimensions highlights Drawing Slow Dimension 1.3" 33.9" 0.100" 0.135" 0.135" 0.135"	(Step FA) ghted on inspection sheet Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN MIN MIN	Actual Dimension 1.23 33.575 121 112	Accept	Reject	Method of Inspection	f Comm
Inspect dimensions highlights Drawing Slow Dimension 1.3" 33.9" 0.100" 0.135" 0.135" 0.135"	(Step FA) ghted on inspection sheet Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN MIN MIN	Actual Dimension 1.23 33.575 121 112	Accept	Reject	Method of Inspection	f Comm
Inspect dimensions highlights Drawing USION Dimension 1.3" 33.9" 0.100" 0.135" 0.135" 0.135" 0.135" 1.4-7	(Step FA) ghted on inspection sheet Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN MIN MIN	Actual Dimension 1.23 33.575 121 112	Accept	Reject	Method of Inspection	for Rou 13

Approved

1-

Revised by

Change New Issue

Rev

Date

	DART AEROSPACE LTD			WORK O	KUEK:	40587
Description: Seat Pan (Aft	Facing)			Part No	umber:	D37741
Inspection Dwg: D377	′4 Rev: <i>从</i> 分					Page 1 of
		01.01.26				चार • व
			ION CIT			हरू ह
	FIRST ARTIC	LE INSPECT	ION CH	ECKLIST		ं के: 470: हुके
. /	⊠ First	Article [Protot	ype		ener
\$ S		_		• 1		1 m
		(4) Thermo				4
•	Visua	l Inspection	Sign-of	f		
Description	-				··· - -	Initials
Description						
Acceptable shape definition						B
Free of visual flaws (bumps	s, cracks, voids, etc.)					- B
						
	(5	Step 6) Trim	ming			
Inspect dimensions highli		FAI Check	list	Rev and	record b	elow
Inspect dimensions highli		FAI Check	list	Reject	Method c	of Comme
_	ghted on inspection sl	FAI Check	list	Reject		of Comme
Drawing Slows Dimension 1.3"	ghted on inspection sl	FAI Check	Accept	Reject	Method c	of Comme
Drawing	ghted on inspection sl	FAI Check	Accept	Reject	Method c	of Comme
Drawing	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN MIN	Actual Dimension 1247 33.875	Accept	Reject I	Method c	of Comme
Drawing 5 00 5 Dimension 1.3" 33.9" 0.100" 0.135" 0.135" 0.135"	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN	Actual Dimension 1247 33.875	Accept	Reject I	Method c	of Comme
Drawing 5 0NS Dimension 1.3" 33.9" 0.100" 0.135" 0.135" 0.135" 0.135"	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN	Actual Dimension	Accept	Reject I	Method c	of Comme
Drawing 5 00 5 Dimension 1.3" 33.9" 0.100" 0.135" 0.135" 0.135"	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN	Actual Dimension 1247 33.875	Accept	Reject I	Method c	of Comme
Drawing 5 0NS Dimension 1.3" 33.9" 0.100" 0.135" 0.135" 0.135" 0.135"	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN	Actual Dimension	Accept	Reject I	Method c	of Comme
Drawing 1.3" 33.9" 0.100" 0.135" 0.135" 0.135" 0.135" 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN	Actual Dimension	Accept	Reject	Method c	of Comme
Drawing 1.3" 33.9" 0.100" 0.135" 0.135" 0.135" (7.4)	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN MIN MIN MIN MIN MIN MIN	Actual Dimension 1247 33.575 90 171 162 152 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4 17.4	Accept	Reject	Method conspection	of Comme
Drawing 1.3" 33.9" 0.100" 0.135" 0.135" 0.135" 0.135" 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.2 1.	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN	Actual Dimension 1247 33.875 90 171 162 120 152 17-4	Accept	Reject	Method conspection	of Comme
Drawing 1.3" 33.9" 0.100" 0.135" 0.135" 0.135" 1.2	ghted on inspection sl Tolerance +/- 0.100 +/- 0.100 MIN	Actual Dimension 1247 33.875 90 171 162 120 152 17-4	Accept	Reject	Method conspection	of Comme in



Ami: CHENTAL

GE Polymershapes

1250 OLD INNES RD. 519 OTTAWA, ONT. K1B 5L3 TEL: 613 745 7043 FAX: 613 745 8163

CERTIFICATE OF COMPLIANCE

SOLD TO: DART AEROSPACE

DATE:8/17/2007

YOUR PURCHASE ORDER: PO00004161

OUR SHIPPER NO: 078178

LINE ITEM # .1

QUANTITY: 81

DESCRIPTION: F60029 LEXAN GY3778 125 X 48 X 96

THESE PARTS WERE MANUFACTURED IN ACCORDANCE WITH: FAR 25. 853

THIS IS TO CERTIFY THAT THE MATERIAL FINISHES AND FUNCTIONAL REQUIREMENTS OF THE ABOVE LISTED PARTS ARE IN ACCORDANCE WITH THE REFERENCE PROCUREMENT SPECIFICATIONS, CONTROL DRAWINGS OR PARTS DESIGNATION AND LATEST REVISIONS AS REFERENCED ON THE SUBJECT PURCHASE ORDER.

AUTHORIZED REPRESENTATIVE SIGNATURE

JON CALDWELL BRANCH MANAGER

613745424291 To:6136321053

Dalder et

AUG-17-2007 08:15 From: GE POLYMERSHAPPES

Receiving Report Batch No: Date: pullshars Dart P/O: Supplier: No Release Note Attached: Yes Packing Slip: Yes Waybill Attached: Yes No Invoice: Yes No Yes, N/A Shipment Complete: Cr Receipt: Cash N/A QC6 Inspection Par Mode N/A Work Order Discrepancies Quantity Quantity Quantity * Quantity Part Comments Description Short Ordered Received Returned Number Level 12 Initials of receiver (if shipment OK) Production/Admin: Location Date

H:\FORMS\Purchasing\approved purch\RECREPORT Rev D


Received/Costing

Initial

		** PLEASE NOTE: IF YOU WE FAXED OR E-MAILED TO YOU INVOICE TO OUR BRAMPTON : THANK YOU EMAIL/FAX INFO	PLEASE MAIL OR FA	X A COPY OF THIS
	ď			
Nager Service				
And Septime And S				

PLEASE Remit To: GE Polymershapes 9150 Airport Road Brampton ON L6S 6G1 Tel: 905-789-3111 Fax: 905-789-3152 NO GOODS TO BE RETURNED WITHOUT APPROVAL FROM US. ALL DISCREPANCIES MUST BE REPORTED WITHIN 3 DAYS.

D3774-1 SEAT BOTTOM



SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO 40 587

D3774-3 SEAT BACK



					1	
В	UPDATE 3); UPD HOLES REASO	E CUTOUT DIM ATE MINIMUM ON D3?74-3 (Z N: MANUFACTI	PH	08.07.25		
Α	NEW ISSUE			HS	08.06.23	
REV.	DESCRIPTION			BY	DATE	
DESIG	4	HS	DART AEROSP	ACE L	TD	
DRAW	٧	PE	HAWKESBURY, ONTAF			
CHECK	ED	1	DRAWING NO.		REV. B	
MFG. A	PPR.	DUD	D3774	SHEET 1 OF 3		
APPRO	VED	111	TITLE		SCALE	
DE APF	PR.	-11	SEAT		NTS	
DATE 08.07.25 COPYRIGHT © 2008 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONTENTUAL AND IS UPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT						

8

5

